


▲ Monument Description: Brass spike (9" long x 1/2" dia. with 1-1/2" dia. brass cap in brass plate) was found 0.2' below grade State Plane Grid Coordinates: Northing: 1437401.9', Easting: 3094523.2'		
SHEET 1 OF 2	MONUMENT RECORD CORNER ID: RICH_W17	Quarter Corner Section 24 & 25-T09N-R02W Richland Township Monroe County, Indiana
 MONROE COUNTY SURVEYOR'S OFFICE Trohn Enright-Randolph Monroe County Surveyor Rachel Savich Oser Professional Surveyor 119 West 7th Street, Bloomington, IN 47404 (812) 349-2570		

Photos were taken on 12/13/2017 with an iPhone 6s



Origin: The Monroe County Surveyor's Office replaced an iron pin found 0.9' below the asphalt surface of Smith Pike with a 9" brass spike in a plate on September 21, 1999. The County Surveyor indicated that the iron pin he replaced could have been a crimped iron pipe. The monument was accepted by the Monroe County Survey Review Board on October 21, 1999.

History: This corner is shown on a 1972 and a 1991 survey by Raymond Graham, but a monument type is not indicated. In 1993, Michael Mundy (Survey Book 3, page 32) found an iron pin at this corner and Ben Bledsoe (Survey Book 2, page 400) found a railroad spike. The railroad spike was accepted by multiple surveyors with no mention of the iron pin until 1999 when the County Surveyor said he replaced it with a brass spike. The brass spike has been accepted on every recorded survey since it was set. When the iron pin was replaced in 1999, it was 9" below grade. Smith Pike is a busy road, so maybe there has always been one monument, and it was incorrectly identified in the past.

Search Procedure: This monument is 1.5' west of the centerline of Smith Pike. We did not utilize any subsurface investigation techniques (such as ground penetrating radar or excavation) to look for a stone. We used a metal detector to search a 5' radius around the brass spike (just in case there was actually a second monument) but did not get a sounding.




Trohn Enright-Randolph
Trohn Enright-Randolph
Monroe County Surveyor



Accepted by the Monroe
County Surveyor Review Board
on November 21, 2017



Rachel Oser
Rachel Savich Oser, State of Indiana
Professional Surveyor No. 21100022

SHEET 2 OF 2	MONUMENT RECORD CORNER ID: RICH_W17	Quarter Corner Section 24 & 25-T09N-R02W Richland Township Monroe County, Indiana	 MONROE COUNTY SURVEYOR'S OFFICE Trohn Enright-Randolph Monroe County Surveyor Rachel Savich Oser Professional Surveyor 119 West 7th Street, Bloomington, IN 47404 (812) 349-2570
-----------------------	---	---	---

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 25

Township: 9 North

Range: 2 West

Corner ID: Rich W-17


Monument Description & Remarks: Replaced iron pin (found 0.9' below asphalt surface of Smith Pike) with 9" Brass Spike with Plate at the North ¼ corner of section. Note: iron pin could have been a crimped iron pipe.

References On File: Survey by Mike Mundy, R.L.S. No. 880014, recorded in Book 3, Page 32, in the County Recorder's Office. Survey by Bledsoe Tapp & Co., recorded in Book 4, Page 258 in the County Recorder's Office.

RECOVERY TIE DRAWING

Field Book 99-01 Page No. 50

USGS Bloomington Quad



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 21st day of September, 1999.

Kevin P. Enright

Administered by the Monroe County Surveyor Review Board

Date: 10/21/99

